

## PICTURE REFERENCES SAMPLE

Picture 1



The flat roof areas over the Arizona room and back patio are in poor condition.

Picture 2



The flat roof areas over the Arizona room and back patio are in poor condition.

Picture 3



The flat roof areas over the Arizona room and back patio are in poor condition.

Picture 4



There is a crack in the seal around the water heater vent pipe.

Picture 5



The wood around the chimney is in poor condition.

Picture 6




There are termite tubes on the back patio.

Picture 7




There are termite tubes on the back patio.

Picture 8



There is no vacuum breaker where the landscape watering system connects to the water main.

Picture 9



There is damaged wood at the roof below the front of the carport.

Picture 10



There is damaged siding at the back of the house.

Picture 11



There is damaged wood trim at the side of the carport.

Picture 12



There is an off-set in the driveway that could be a trip hazard.

Picture 13



There is vegetation overgrowing the walls/roof.

Picture 14



There is vegetation overgrowing the walls/roof.

Picture 15



The washer and dryer are powered with an extension cord.

Picture 16



The water heater pressure relief drain line terminates in the laundry room.



Picture 17



It appears the duct for the hallway bathroom exhaust fan terminates in the attic.

Picture 18



The security system component installed on the master bedroom window blocks the window from being opened.